



June 3, 2010

Red Point Development
8710 North Thornydale Road
Tucson, Arizona 85742

Attn: Mike Leung

**RE: Mitigation of Uncontrolled Fills on Lots 1-6, 15-19, 70-78, and 115
Phase I Residential Development at the Pines
At the Pines Golf Course
North of Cortaro Road and West of Interstate 10
Marana, Arizona
Terracon Project No. 63101060**


Terracon has completed the geotechnical engineering report for the Residential Development at the Pines (Terracon Project 63045525, dated December 8, 2004). Addendum No. 10, Revision No. 1, dated October 15, 2008, addressed a portion of the property where uncontrolled fills between 7 and 27 feet deep existed. Recommendations to remove and re-compact existing uncontrolled fills in this area were provided.

During March through May of 2010, earthwork was performed on these lots. Terracon monitored earthwork and compaction during this time. The recommendations contained in our Addendum No. 10, Revision No.1, have been followed and the mitigation of the uncontrolled fills is completed. Results of compaction testing during this work are attached.

If you have any questions regarding this letter please contact us.

Sincerely,

TERRACON



Oleg B. Lysyj, P.E.
Principal

Expires 03/31/2012

Copies: Addressee (2)

N:\Projects\2010\6301060\63101060.ltr



Terracon Consultants, Inc. 355 South Euclid, Suite 107 Tucson, Arizona 85719
P [520] 770 1789 F [520] 792 2539 terracon.com

Geotechnical ■ Environmental ■ Construction Materials ■ Facilities